


加工精度	
Max Cutter Dia	ø150(6")
Reduction Ratio	1 : 1
Max Torque	1000N.m
Max Power	38kw
Max Revolving	800rpm
Main Spindle Steering	Right Turn
Accessories : T-Screw X4 M16XP2.0X67L	

Pull Stud Select	BT (M16XP2.0)
	NT (M16XP2.0)
	NT (5/8")





A73-8B(E)


加工精度	
Max Cutter Dia	ø200(8")
Reduction Ratio	1 : 1
Max Torque	1200N.m
Max Power	38kw
Max Revolving	800RPM
Main Spindle Steering	Right Turn
Accessories : T-Screw M18XP2.5X87L X6	

Pull Rod Select	BT(M24X3.0)
	NT(M24X3.0)
	NT(1")

Graduation Ring






6-ø19 Pierce
P.C.D.ø240



A74-3-3(E)

加工精度	
Max Cutter Dia	ø150(6")
Reduction Ratio	1 : 1
Max Torque	1000N.m
Max Power	38kw
Max Revolving	800rpm
Main Spindle Steering	Right Turn
Accessories : T-screw M16XP2.0X67L X4	

Pull Stud Select	BT (M16XP2.0)
	NT (M16XP2.0)
	NT (5/8")



A73-4D(E)