


--

J76	
Max Pevolving	2000rpm

1.T-screw M16XP2.0X67Lx4

M16XP2.0X75LX8

4.Hut M16XP2.0 x8



--

J76	
Max Pevolving	2000rpm

Accessory:

- 1.T-screw M16XP2.0X67Lx4
- 2.Hexagon screw
M16XP2.0X75LX8
- 3.Washer x12
- 4.Hut M16XP2.0 x8

1.T-screw M16XP2.0X67Lx4

M16XP2.0X75LX8

4.Hut M16XP2.0 x8

