









手動鎖刀 / 手動轉角度

拉 桿 選 項	BT(M24X3.0)
	NT(M24X3.0)
	NT(1")
附件：T型螺栓 X4支 M16XP2.0X72L	

使用最大刀具直徑	ø150(6")
減 速 比	1 : 1
最 大 扭 矩	1000 N.m
最 大 馬 力	35kw
最 高 轉 速	2000rpm
主 軸 轉 向	正 轉
本體旋轉角度	可360度旋轉
主軸頭旋轉角度	工作角度左右各90度 容許角度左右110度



H45-7






Lock cutter by manual /
Rotate angular by manual

Pull Stud Select	BT(M24X3.0)
	NT(M24X3.0)
	NT(1")


Accessories : T-Screw X4
M16XP2.0X72L

Max Cutter Dia	$\phi 150(6")$
Reduction Ration	1 : 1
Max Torque	1000 N-m
Max Power	35kw
Max Revolving	2000rpm
Main Spindle Steering	Right Turn
Substance rotate the angle	angle rotates 360°
Swing milling head rotate the angle	The job angle rotates 90° upwards Permit the angle to rotute 110° upwards






Lock cutter by manual /
Rotate angular by manual





Pull Stud Select	BT(M24X3.0)
	NT(M24X3.0)
	NT(1")
Accessories : T-Screw X4 M16XP2.0X72L	

Max Cutter Dia	ø150(6")
Reduction Ration	1 : 1
Max Torque	750 N.m
Max Power	35kw
Max Revolving	3000rpm
Main Spindle Steering	Right Turn
Substance rotate the angle	angle rotates 360°
Swing milling head rotate the angle	The job angle rotates 90° upwards
	Permit the angle to rotute 110° upwards



H45N-4(E)



Lock cutter by manual /
Rotate angular by manual

Pull Stud Select	BT(M24X3.0)
	NT(M24X3.0)
	NT(1")

Accessories : T-Screw X4
M16XP2.0X72L

Max Cutter Dia	$\phi 150(6")$
Reduction Ration	1 : 1
Max Torque	750 N.m
Max Power	35kw
Max Revolving	3000rpm
Main Spindle Steering	Right Turn
Substance rotate the angle	angle rotates 360°
Swing milling head rotate the angle	The job angle rotates 90° upwards Permit the angle to rotute 110° upwards

