




加工精度	
------	--




SHIFTING MECHANISM	HYDRAULIC CHANG HIGH AND LOW (NO INCLUDING OIL TANK)	
REDUCTION RATIO	1 : 1.94	1 : 6.78
MAX. REVOLVING	3000 rpm	
TRAVEL	800mm (BALLSCREWS)	
TAPER OF SPINDLE NOSE	#50	
DRAW BAR	HYDRAULICE TYPE (NO INCLUDING OIL TANK)	
MAX. CUTTER DIA	ø300	
MAX. FEED SPEED	6000mm/min	
PULL STUD	☐ MAS ☐ DIN ☐ CAT ☐ _____	
INC :HYDRAULIC CYLINDER (NO INCLUDING OIL TANK)		



加工精度	
------	--




MAIN SPINDLE MOTOR	AC 25HP FREQUENCY CHANGEABLE	
SHIFTING MECHANISM	MANUAL CHANG HIGH AND LOW	
REDUCTION RATIO	1 : 1.94	1 : 6.78
MAX. REVOLVING	1800 rpm	
TRAVEL	1000mm	
TAPER OF SPINDLE NOSE	#50	
DRAW BAR	AIR POWER DRAWBAR (NO INCLUDING AIR COMPRESSOR)	
MAX. CUTTER DIA	ø300	
MAX. FEED SPEED	6000mm/min	
PULL ROD SELECT		BT(M24XP3.0)
		NT(M24XP3.0)
		NT(1")
INC :HYDRAULIC CYLINDER (NO INCLUDING OIL TANK)		




UNDERSIDE VIEW

U70-A2(E)

加工精度	
------	--





SHIFTING MECHANISM	HYDRAULIC CHANG HIGH AND LOW (NO INCLUDING OIL TANK)	
REDUCTION RATIO	1 : 1.94	1 : 6.78
MAX. REVOLVING	3000 rpm	
TRAVEL	1000mm (BALLSCREWS)	
TAPER OF SPINDLE NOSE	#50	
DRAW BAR	HYDRAULICE TYPE (NO INCLUDING OIL TANK)	
MAX. CUTTER DIA	ø300	
MAX. FEED SPEED	6000mm/min	
PULL STUD	☐ MAS ☐ DIN ☐ CAT ☐ _____	
INC :HYDRAULIC CYLINDER (NO INCLUDING OIL TANK)		




U71-A3(E)

--



MAIN SPINDLE MOTOR	AC 30HP FREQUENCY CHANGEABLE	
SHIFTING MECHANISM	MANUAL CHANG HIGH AND LOW	
REDUCTION RATIO	1 : 1.94	1 : 6.78
MAX. REVOLVING	1800 rpm	
TRAVEL	800mm	
TAPER OF SPINDLE NOSE	#50	
DRAW BAR	AIR POWER DRAWBAR (NO INCLUDING AIR COMPRESSOR)	
MAX. CUTTER DIA	ø300	
MAX. FEED SPEED	6000mm/min	
PULL ROD SELECT		BT(M24XP3.0)
		NT(M24XP3.0)
		NT(1")
INC :HYDRAULIC CYLINDER (INCLUDING OIL TANK) Variable-frequency Drive		



BACK VIEW UNDERSIDE VIEW

U60-A3(E)