




加工精度

Pull Stud Select	BT(M24X3.0)	Max Cutter Dia	ø150(6")
	NT(M24X3.0)	Reduction Ratio	1 : 1
	NT(1")	Max Torque	1000N.m
		Max Power	38kw
		Max Revolving	2000rpm
		Main Spindle Steering	Right Turn
Accessories :			
T-Screw M16XP2.0X67L X2			
T-Screw M16XP2.0X76L X3			




C45N-01(E)





C45-4C(E)


加工精度

Pull Stud Select	BT(M24X3.0)	Max Cutter Dia	ø150(6")
	NT(M24X3.0)	Reduction Ratio	1 : 1
	NT(1")	Max Torque	1000N.m
		Max Power	38kw
		Max Revolving	2000rpm
		Main Spindle Steering	Right Turn
Accessories :			
T-Screw M16XP2.0X67L X2			
T-Screw M16XP2.0X76L X3			



C45N-02(E)





加工精度

Accessories: "T"-Screw x5
M18XP2.5X87L


Max Cutter Dia	φ150(6")
Reduction Ratio	1 : 1
Max Torque	1200N.m
Max Power	42kw
Max Revolving	2000 RPM
Main Spindle Steering	Right Turn

Pull Stud Select	BT(M24X3.0)
	NT(M24X3.0)
	NT(1")

4-M10
P.C.D.φ98

5-φ19 Pierce
P.C.D.φ240

Graduation Ring
0°~360°



C50N-01(E)

加工精度

Pull Stud
Select

BT(M24X3.0)
NT(M24X3.0)
NT(1")

Max Cutter Dia	ø150(6")
Reduction Ratio	1 : 1
Max Torque	1200Nm
Max Power	42kw
Max Revolving	2000rpm
Main Spindle Steering	Right Turn

Accessories :
T-Screw M18XP2.5X87L

